

(4)
11/2/94

LIGHTNING STRIKE ON
Pinus Torryana, PLAYGROUND,
PUKEKURA PARK.

CHOKE MELTED DOWN BUT LAMP
AND CABLE UNHARMED.

The charge must have
dissipated in destroying
the choke.

G. FULLER.

(5)

11/2/94

PATH OF LIGHTNING STRIKE
ON *Pinus torrauana*, PLAYGROUND,
PUKEKURA PARK.

Note how the charge
has jumped from the
central leader to that
on the left then directly
down to the light fitting
where it terminated in
burning out
the choke.

G. FULLER.

16
16/9/03

Rot resulting from lightning
strike (Feb. 1994) on *Pinus*
torreyana, playground,
Pukekura Park.

INFOCUS <No.16 >016
935 4012-1 N-1-1 04 2(024)

G. Fuller.